

Figure 1. Comparison of the mean number of bacteria present on the stomach flushing tube after being cleaned using Milton.




Figure 2. Comparison of the effectiveness of three cleaning products to remove three known bacteria from a stomach flushing tube.

